
LOAD/UNLOAD OPERATION CONTROL METHOD . . . Hirano et al. Greer, Burns & Crain, Ltd. (Patrick Burns) Ref. No. 0941.65876 Sheet 1 of 20 (312) 360 0080



F1G. 1A

-16. 1B




FIG.3




FIG.4




FIG.5




FIG.6




FIG.7






FIG.8




LOAD/UNLOAD OPERATION CONTROL METHOD . . . Hirano et al.
Greer, Burns & Crain, Ltd. (Patrick Burns)
Ref. No. 0941.65876
Sheet 7 of 20 (312) 360 0080





F16.


LOAD/UNLOAD OPERATION CONTROL METHOD . . . Hirano et al.
Greer, Burns & Crain, Ltd. (Patrick Burns)
Ref. No. 0941.65876
Sheet 8 of 20 (312) 360 0080 $\widehat{\mathbf{H}}$ $\widehat{\mathbb{H}}$ (E)(E)<u>e</u> 9 <u>@</u> (B) 3 3 INNER OUTER OUTER INNER FIG. 10A VCM CURRENT — FIG. 10B VCM CURRENT


FIG. 11












LOAD/UNLOAD OPERATION CONTROL METHOD . . . Hirano et al. Greer, Burns & Crain, Ltd. (Patrick Burns) Ref. No. 0941.65876 Sheet 14 of 20 (312) 360 0080



LOAD/UNLOAD OPERATION CONTROL METHOD . . . Hirano et al. Greer, Burns & Crain, Ltd. (Patrick Burns) Ref. No. 0941.65876 Sheet 15 of 20 (312) 360 0080






FIG.18




LOAD/UNLOAD OPERATION CONTROL METHOD . . . Hirano et al.
Greer, Burns & Crain, Ltd. (Patrick Burns)
Ref. No. 0941.65876
Sheet 17 of 20 (312) 360 0080



F1G. 1

LOAD/UNLOAD OPERATION CONTROL METHOD . . . Hirano et al. Greer, Burns & Crain, Ltd. (Patrick Burns) Ref. No. 0941.65876 Sheet 18 of 20 (312) 360 0080



LOAD/UNLOAD OPERATION CONTROL METHOD . . . Hirano et al.
Greer, Burns & Crain, Ltd. (Patrick Burns)
Ref. No. 0941.65876
Sheet 19 of 20 (312) 360 0080

